



REPAIR TO ROTADISC DRIER

Tenix Robt Stone was awarded a contract to carry out repairs to the rotor of a disc drier from By Products. The rotor was extracted from the drier by Tenix Robt Stone's Hawera branch and transported to the New Plymouth workshop.

Repairs carried out in the New Plymouth workshop included:

- Welding repairs to the cracked welds in the disc dowels
- Welding overlay of the disc outer rims
- Replacement and reversing of all kicker plates
- Replacing of the inlet paddles
- Reversing of the inlet steam pipe
- Hydro testing of the completed unit

Following repairs the rotor was transported back to the plant where it was re-inserted in the drier stator. A similar repair was carried out to another Rotadisc Drier in 1999.

- **PROJECT:** REPAIR TO DISC DRIER
- **CLIENT:** BY PRODUCTS
- **LOCATION:** HAWERA, NEW ZEALAND
- **DATE:** 2002
- **CONTRACT VALUE:** \$ 20,000